



Attorney Docket No. 837.1979

IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

In re Patent Application of:

Fumitake SUZUKI, et al.

Application No.: 10/046,223

ATTENTION

Confirmation No.: 4399

CERTIFICATE OF CORRECTION

Filed: January 16, 2002

BRANCH

U.S. Patent No.: 6,715,934 B2

Batch No.:

Issued: April 6, 2004

For: RECEPTACLE TYPE OPTICAL MODULE AND PRODUCTION METHOD THEREFOR

**REQUEST FOR CERTIFICATE OF CORRECTION**

Commissioner for Patents  
PO Box 1450  
Alexandria, VA 22313-1450

Sir:

Patentees respectfully request that a Certificate of Correction be issued in the subject patent, pursuant to 35 USC § 254 and 37 CFR § 1.322, to correct the error shown on the attached Form PTO-1050. A check in the amount of \$100 to cover the cost of the Certificate is attached.

One or more of the errors shown on the attached Form PTO-1050 is or are within the responsibility of the undersigned; each thereof is of a clerical or typographical nature or of minor character and occurred in good faith, and the correction thereof is consistent with the prosecution record.

05/17/2004 WABRHAM2 00000220 6715934

01 FC:1811

100.00 OP

Respectfully submitted,

STAAS & HALSEY LLP

Date: May 14, 2004

By:

  
Gene M. Garner II  
Registration No. 34,172

1201 New York Ave, N.W., Suite 700  
Washington, D.C. 20005  
Telephone: (202) 434-1500  
Facsimile: (202) 434-1501

MAY 20 2004

**Best Available Copy**

Under the Paperwork Reduction Act of 1995, no persons are required to respond to a collection of information unless it displays a valid OMB control number.  
(Also Form PTO-1050)

UNITED STATES PATENT AND TRADEMARK OFFICE  
CERTIFICATE OF CORRECTION

PATENT NO : 6,715,934 *B2*

DATED : April 6, 2004

INVENTOR(S) : Fumitake SUZUKI, et al.

Column 8, line 29, delete "rein" and insert --resin--.

MAILING ADDRESS OF SENDER:  
STAAS & HALSEY LLP  
1201 New York Ave., N.W.  
Suite 700  
Washington, DC 20005

PATENT NO. 6,715,934 *B2*

No. of add'l copies  
@ 50¢ per page

MAY 20 2004

Best Available Copy